

# Oil Field Environmental Incident Summary

**Incident:** 20160225041021      **Date/Time of Notice:** 02/25/2016 04:10  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** CCU ZEPHYR 34-34 TFH  
**Field Name:** CORRAL CREEK      **Well File #:** 32003  
**Date Incident:** 2/24/2016      **Time Incident:** 0830      **Facility ID Number:**  
**County:** DUNN      **Twp:** 147      **Rng:** 94      **Sec:** 34      **Qtr:**  
**Location Description:**

**Submitted By:** Allen Wheeler      **Received By:**  
**Contact Person:** Allen Wheeler  
600 N. DAIRY ASHFORD  
HOUSTON, TX 77079

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	2	Barrels	2	Barrels		

**Description of Other Released Contaminant:**

Oil Based Mud

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

None. Contained on location and cleaned up immediately

**Areal Extent:**

***Potential Environmental Impacts:***

None

***Action Taken or Planned:***

Contained within Berm. Cleaned up with rig vacuum system

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 2/25/2016    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary, this spill remained on location. NDIC retains oversight.